



## Temperaturtabelle

		
<b>40°C</b>	2K-Härter MS 25-40	2K-Härter MS 25-40
<b>30°C</b>	2K-Härter MS X 15-30	2K-Härter MS 25-40 2K-Härter MS X 15-30
<b>20°C</b>	2K-Härter MS X 15-30 2K-Härter MS X 5-25 2K-Härter MS 5-15	2K-Härter MS X 15-30
<b>10°C</b>	2K-Härter MS X 5-25 2K-Härter MS 5-15	2K-Härter MS X 5-25
<b>5°C</b>		